

SGS ITALIA S.p.A.

**Industries & Environment** Via Caldera, 21 20153 Milano

Tel. (02) 7393.1 Fax: (02) 70125067

Affiliate code 095103

Pagina 1 di 2 Page 1 of 2

# CERTIFICATO D'ISPEZIONE NR. 0419/VE (ÍNSPECTION CERTIFICATE)

Data: 10/01/2023

FILE NO. 21.20137

**FORNITORE** SUPPLIER

LEGHORNGROUP SRL - VIA DEGLI ARROTÍÑI 34/36 - LIVORNO

COSTRUTTORE MANUFACTURER LEGHORNGROUP SRL - VIA DEGLI ARROTINI 84/36 - LIVORNÓ

# **DESCRIZIONE MATERIALE / MATERIAL DESCRIPTION**

Prodotto sottoposto all'attività' / Product object of the test

**CABLE SEAL 4MM** 

#### ISPEZIONE ESEGUITA / INSPECTION PERFORMED

Sono state presenziate le prove di antimanomissione di sigillo di alta sicurezza CABLE SEAL 4MM previste dalla norma ISO 17712:2013 punto 6.

The tamper-evident capabilities test of high-security seal CABLE SEAL 4MM have been witnessed according to ISO 17712:2013 clause 6.

### DOCUMENTI DI RIFERIMENTO I REFERENCE DOCUMENTS

Le prove effettuate sul materiale sono state eseguite in conformità con i seguenti documenti: Activities have been performed according to the following documents:

- STANDARD ISO 17712:2013 clause 6.
- LEGHORNGROUP TEST REPORT NO. 0001 2022/12/15 finalized on 2022/12/22

#### **RISULTATI / RESULTS**

I risultati ottenuti dalle verifiche e dai collaudi effettuati sono riportati in dettaglio nei seguenti documenti: The test results of the activities performed are detailed in the following documents

Inspection report No 0001 - 2022/12/15 finalized on 2022/12/22, issued by Leghorngroup and witnessed by SGS and SGS inspection report N° 23.500.0029 rev.0 dated 10/01/2022.

Member of SGS (Société Générale de Surveillance) Group

Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is pot responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party and the results. party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.

FT 06/12

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's finding at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility into its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligation under the transaction documents

SGS Italia S.p.A. On behalf of Business Manager A. Michelini

20303929





SGS ITALIA S.p.A.

**Industries & Environment** 

Via Caldera, 21 20153 Milano

Tel. (02) 7393.1 Fax: (02) 70125067

Affiliate code 095103

CERTIFICATO D'ISPEZIONE NR. 0419/VE (INSPECTION CERTIFICATE)

Data: 10/01/2023 FILE NO. 21.20137

> agina 2 di 2 Page 2 of 2

# CONCLUSIONI / CONCLUSIONS

Le prove di antimanomissione effettuate sono risultate, per le attività eseguite, conformi al requisiti dei documenti di riferimento e in particolare alla norma ISO 17712:2013 punto 6.

The appropriate testing activities have been performed and the results conform to the requirements outlined in ISO 17712:2013 clause 6.

- This Certificate Is Composed of 2 Pages -

Above findings are limited to the date and place of intervention only. The company is neither an insurer nor a guarantor and disclaims all liability in such capacity. Our inspection/certification does not absolve the manufacturer/seller from their contractual obligations towards their buyer.

Member of SGS (Société Générale de Surveillance) Group

Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/faboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safety and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents

SGS Italia S.p.A. 🔪 On behalf of Business Manager A. Michelini

